

Name: \_\_\_\_\_

# CDL Inspection Section 4 & 5

- |   |                             |
|---|-----------------------------|
| 1. Valve stem is straight_____ - ____.  | A. fittings leaks           |
| 2. Tire_____ has been checked with a _____ and is at manufacturer's specification.      | B. Broken                   |
| 3. Top of tire is_____ evenly with at least 4/32 inch tread remaining.                  | C. with a cap               |
| 4. Grab the Mirror - It's firmly_____, not broken & clean.                              | D. Breakers                 |
| 5. Open the Door - It_____ & _____ properly, _____ are tight, _____ is not torn.        | E. triangles                |
| 6. _____ roll up and down   | F. closed                   |
| 7. There are no _____ under the pedals.   | G. vented tight             |
| 8. There is a 10 BC fire extinguisher properly charged & _____                          | H. obstructions             |
| 9. Battery box & _____ are properly attached to the _____.                              | I. Tight                    |
| 10. Battery Box 4 12v   | J. cover frame              |
| 11. Battery Box Cell Caps   | K. straps gasket            |
| 12. Steps Mounted   | L. Windows                  |
| 13. Steps Not   | M. pressure gauge           |
| 14. Steps Not   | N. batteries                |
| 15. Tank is mounted to the frame with_____, there's a _____ between the strap and tank. | O. attached                 |
| 16. Fuel lines & _____ have no cuts, cracks, frays or _____. No leaks under the tank.   | P. wearing                  |
| 17. There is a _____ fuel cap with gasket & it is_____.                                 | Q. holes tears              |
| 18. Sleeper has no _____ or _____ in the skin.  | R. Securely                 |
| 19. Inside this door 3 warning  | S. mounted                  |
| 20. Inside this door Spare Fuses or   | T. Cracked                  |
| 21. This inside Door is   | U. opens closes hinges seal |